



Supervision:

Sl. No.	Client Name	Description of Job
1	Dalmia Cement (Bharat) Ltd., Ariyalur	Supervision of Kiln Cowl shell and Graphite Block Replacement
2	The India Cement Limited, Dalavoi	Supervision of Thrust Roller Replacement
3	The India Cement Limited, Sankari	Ball Mill Inlet Head Replacement
4	Keerthi Industries Ltd, Mellacheruvu	Kiln Support Roller Replacement & Coal Mill Girth Gear Reversal
5	Ambuja Cement Limited, Ropar	Cement Mill Discharge Head Replacement
6	ACC Limited, Kymore Cement Works	Kiln Support Adjustment and Cooler Alignment Check
7	UltraTech Cement Ltd., Jharsguda Cement Works	Cement Mill Outlet Bearing Replacement
8	JK Lakshmi Cement, Sirohi	Kiln Support Roller Replacement
9	Ambuja Cement Limited Rabriyawas Cement Works	Kiln Shell Profile Study
10	Ambuja Cement Ltd, Darlaghat Cement Works	Kiln Shell Replacement (Inlet shell with tire total 12 meters) including ground assembly
11	Davao Cement, Philippines	Kiln axis correction and thrust balancing of Kiln
12	JK Lakshmi Cement Ltd., Sirohi	Slide shoe bearing replacement of ball mill
13	Saurashtra Cement Limited, Ranavav	Root cause analysis of the vibration of the ball mill girth gear
14	KJS Cement (I) Ltd., Satna	Kiln Shell and Cowl Shell Replacement
15	JK White Cement Works, Gotan	Kiln Middle Tire Wear Ring Replacement
16	Saurashtra Cement Limited, Ranavav	Trouble Shooting Job in VRM
17	Ambuja Cement Limited, Darlaghat	Supervision of Ball Mill head replacement
18	TATA Chemical Ltd., Mithapur	Cement Mill Vibration Issue Trouble Shooting
19	Andritz (China) Limited, China	Kiln Girth Gear and Pinion Replacement
20	Nuvoco Vistas Corporation Ltd, Jojobera	Cement Mill Vibration Issue Trouble Shooting
21	JK Lakshmi Cement Ltd., Sirohi	Cowl Shell Replacement at Kiln #3



22	Raysut Cement Co., Oman	Supervision of Kiln Shell Replacement
23	Saurashtra Cement Limited, Ranavav	Cooler Alignment Job
24	Shree Digvijay Cement Ltd, Jamnagar	Cooler Maintenance Job
25	Ambuja Cement Limited, Rabriyawas	Cooler Alignment & HTD Replacement Job
26	ACC Limited, Lakheri	Kiln Shutdown job
27	The India Cements Ltd, Sankari, Salem	Cement Mill Inlet Head Replacement
28	ACC- Chanda - Chandrapur	Kiln Trouble Shooting
29	Dalmia Cement (Bharat) Limited, Belgaum	Tire Alignment and retainer block
28	The India Cements Ltd, VishnuPuram	Kiln Support Adjustment
29	The India Cements Ltd, Yerraguntla	Raw Mill Girth Gear Inspection
30	The India Cements Ltd, Sankari,	Inlet tire, middle tire and Outlet tire shim installed & Four Chair pad replacement at Outlet Tire
31	Zuari Cement Ltd., Yerraguntla	Slide shoe Bearing Replacement
32	Asian Fine Cement Ltd., Patiala, Punjab	Slide shoe Bearing Replacement
33	JK Lakshmi Cement Ltd., Sirohi	Kiln Shell Replacement Kiln # 3
34	Ambuja Cement Ltd., Ropar	Cement Mill Inlet Head Replacement
35	Ultratech Cement Ltd., Hirni	Cement Mill Trunnion Bearing Replacement
36	Saurashtra Cement Ltd., Ranavav	Raw Mill FRM 4 Roller Seal Replacement, Kiln Shell Replacement and Cooler Alignment
37	JK Paper Limited, Tapi, Gujarat	Kiln Alignment
38	Ultratech Cement Ltd., JHAJJAR	Ball Mill Header Replacement
39	Ultratech Cement Ltd., Maihar, M.P.	Kiln Grith Gear Inspection
40	Shubshree Agni Cement, Nepal	Supporting Roller Replacement
41	Ras Al Khaima Cement, UAE	Cooler Inspection and Alignment
42	Hindalco industries Ltd, Odissa	Tyre Replacement
43	Paradeep Phosphates Limited, Paradeep	Dryer Erection
44	Kesoram Industries Cement, Ramagudam	Support Roller Replacement and Axis measurement



45	Dalmia Cement (Bharat) Limited, Belgaum	Kiln Shutdown Job
46	JK Lakshmi Cement, Sirohi,	Kiln Shutdown Job
47	Ambuja Cement Limited, Maratha,	Slide Shoe Bearing Replacement
48	Ultratech Cement Limited, Dankuni, Kolkata	Cement Mill Drive Vibration issue
49	ACC Ltd – Lakheri Cement Works, Lakheri,	Kiln Tire Alignment
50	Birla Corp. Limited, Birla Vikas	Roller Press Gearbox Replacement
51	Dalmia Cement (Bharat) Limited, Dalmiapuram	Hot Bearing trouble shooting.
52	Udaipur Cement Works Ltd	Kiln erection supervision.
53	The India Cement Ltd, Vishnupuram	Kiln shell buldge repair job..
54	Saurashtra Cement Ltd	Cooler and Cement Mill GG alignment job.
55	Shree Digvijay Cements Ltd	Cooler Shutdown jobs.
56	Ultratech Cement Ltd, Jhajjar	Roller press replacement job.
57	The India Cements Ltd, Malkapur	Kiln support roller replacement job.
58	The India Cements Ltd, Vishnupuram	Kiln hot bearings issue troubleshooting.
59	Ambuja Cement Ltd, Maratha Cement Works	Kiln shutdown Supervision Jobs.
60	ACC Ltd, Kymore Cement Works	Kiln 1 and 2 shutdown Supervision.