



**Turnkey Jobs:**

Sl. No.	Client Name	Description of Job
1	Ultratech Cement Ltd, Reddypalayam	Kiln shell replacement of 21 meters
2	Zuari Cement Limited, Sitapuram	Kiln Support Roller and Bucket Elevator Replacement
3	Ultratech Cement Ltd., Balaji Cement Works, Jaggaiahpet Mandal	Hydraulic Roller Press bearing Replacement
4	Zuari Cement Limited, Solapur	Girth Gear Alignment and Overhauling of MAAG LGD Gear Box
5	The India Cements Ltd, Malkapur	Cement Mill Girth Gear Alignment, Pinion Alignment and Drive Alignment
6	Ultratech Cement Ltd., Balaji Cement Works, Jaggaiahpet Mandal	Hydraulic Roller Press bearing Replacement
7	Ambuja Cement Limited, Bhatpara	13.5 mtr kiln shell replacement and ESP Bend Duct replacement
8	Birla Corporation Limited, Satna Cement Works	Cement Mill Inlet Head Replacement
9	Ultratech Cement Limited, Maihar	Kiln Tire, Intermediate Shell Girth Gear, Inlet & outlet seals, Outlet Shell & Chair pads Replacement
10	Penden Cement Authority Limited, Bhutan	Major Repair Jobs in Kiln
11	Ultratech Cement Ltd., Maihar Cement Works	Cement Mill Inlet Head Replacement
12	Ultratech Cement Ltd., Sewagram	Ball Mill Slide Ring Grinding & Slide Shoe Bearing Replacement
13	Zuari Cement Limited, Sitapuram	Kiln Middle under tire shell & Chair Pads Replacement and Outlet shell & outlet seals Replacement
14	Nuvoco Vistas Corp.ltd, Arasmeta, Champa	Cement Mill 2 – Girth Gear Replacement
15	Ultratech Cement Ltd., Dalla	Kiln Shell Replacement and Cement Mill – 2 Shell Replacement
16	ACC Ltd – Gagal,	Inlet Tire with Kiln Shell Replacement
17	Tata Chemicals Ltd, Mithapur	Kiln Inlet Tire Replacement
18	Dalmia Cement (Bharat) Limited, Dalmiapuram	16-meter Kiln shell Replacement, Middle Tire Chair Pad Replacement



19	Tata Chemicals Ltd, Mithapur	Ball Mill Outlet shell, head & Girth Gear Replacement
20	Shree Digvijay Cement Ltd, Jamnagar	Kiln Chair pad Replacement
21	JK White Cement Works, Gotan, Rajasthan	Kiln Shell Replacement, in-between Inlet tire and middle tire
22	Paradeep Phosphates Limited, Paradeep	Support Roller and Girth Gear Replacement, Granulator and Cooler
23	Ultratech Cement Limited, Maihar	Kiln Shell Replacement
24	Birla Corporation Ltd, Satna	Kiln Shell Replacement
25	JK Cement Ltd, Mangrol	Kiln Shell Replacement
26	The India Cement Ltd, Vishnupuram	Kiln Support Roller Replacement
27	Dalmia (Bharat) Cement Ltd, Dalmiapuram	14.7 meter kiln shell replacement
28	Birla Corporation Ltd, Satna	Raw Mill Slide Ring In Situ Grinding and Slide Shoe bearing replacement
29	Paradeep Phosphate Limited	Dryer Replacement
30	Paradeep Phosphate Limited	Replacement of tires, trunnions, girth gear pinions, base frames in product cooler and granulator. Of TRAIN A
31	TATA Chemicals Ltd, Mithapur	Cement Mill Shell & Girth Gear Replacement
32	JK White Cement Works, Gotan	10.5 meter kiln shell replacement
33	Ultratech Cement Limited, Hirmi	14 meters kiln shell with girth gear and pinion replacement
34	Ultratech Cement Limited, Arakkonam	Cement Mill Outlet head replacement
35	JK Grey Cement Ltd, Gotan	Kiln 2 no shell section replacement
36	Ultratech Cement Limited, Rawan	Kiln outlet shell and all the three tires chairpad replacement.
37	Paradeep Phosphate Limited	Replacement of tires, trunnions, girth gear pinions, base frames in product cooler and granulator. Of TRAIN B
38	JSW Cement Ltd, Nandiyal	Kiln shell sections replacement (3 pieces) with middle tire.
39	ACC Ltd, Lakheri Cement Works	3 shell section, girth gear replacement and tire all three tire alignment with thruster and inlet tip casting replacement.
40	Tata Chemicals Ltd, Dwarka	Raw Mill head positioning.
41	Birla Corporation Ltd, Birla Vikas	Ball Mill head replacement.
42	Jindal Steel and Power Ltd, Jharsuguda	Kiln shell replacement with girth gear replacement.
43	Ultratech Cement Ltd, Aditya Cement Works	Kiln Inlet Shell replacement.
44	Shree Cement Ltd, Beawar	Kiln 1 outlet shell replacement.